





1. From Valentine Ave. looking north on east property line.



2. Eastern driveway looking slightly northwest at church



3. From eastern side of front lawn, looking west along south property line.



4. From eastern side of front lawn, looking north at church building.



5. Western driveway entrance looking north into parking lot



6. Western parking lot gate looking south towards Valentine Ave.




7. Approximately halfway up western driveway looking northeast at church building



8. Approximately halfway up western driveway looking northeast at church building




9. Approximately halfway up western driveway looking northeast at trash enclosure.



10. Taken from northwestern corner of parking lot looking at furthest northwestern portion of site (existing landscaping).




11. Taken from northwestern corner of parking lot looking at northwestern portion of site (existing landscaping).



12. Taken from northwestern corner of parking lot looking northeast towards parking lot (existing landscaping).




13. Northwestern furthestmost corner of parking lot looking west at parking lot and church building



14. Furthestmost northwestern corner of parking lot looking northwest along northern property line.



15. Centrally located along northern parking lot looking west



16. Centrally located along northern parking lot looking northeast at a small storage shed.



17. Centrally located along northern parking lot looking northeast at a small storage shed.



18. Along northeastern edge of northern portion of the parking lot looking directly south towards church and western driveway entrance.



19. From furthestmost northeastern corner of site looking directly south along eastern property line.



20. From furthestmost northeastern corner of site looking directly west along northern property line.